

CANADIAN ELECTRICAL CODE

SUBJECT: Errata

Following is the latest version (July 29, 2009) of a list of errors that CSA International has identified in the current edition of the Canadian Electrical Code [C22.1-09]. As additional errors are identified, CSA International updates the errata. Please contact CSA if you wish to determine if additional errors have been found. CSA International will make the necessary editorial changes in the next edition of the Code.

Rule 10-618 – Add “(see Appendix B)” to title

Rule 12-112(5)(b) – should read “notwithstanding the requirements of Subrule ~~(3)~~(4)...”

Rule 18-004 – Add “(see Appendix B)” to title

Rule 58-000 – Add “(see Appendix B)” to title

Rule 58-300 – Add “(see Appendix B)” to title

Table 17 – Revise reference rules to read “(See Rules 10-700 and 18-812)”

Table 19 – Under *Conditions of use* “For service entrance above ground” and *Trade designation* “Armoured cable”, reference note 16 applies to AC90, not ACWU90.

Appendix B – Delete note that reads:

“Rule 18-150

A group of three fuses protecting...”

Appendix B – Revise note for rule 18-150(2)(e) to read:

“Rule 18-150(2)(e), 18-210, 18-260, 18-308, 18-358

See the Note to Rule 18-114.”

Appendix B – Delete note that reads:

“Rule 18-150, 18-210, 18-260, 18-308, 18-358

See the Note to Rule 18-114.”

Appendix B – Revise title for note to rule 68-068 to read “**Rule 68-068(6)**”.

Appendix B – Revise title for note to rule 68-306 to read “**Rule 68-306(2)**”.

Reproduced with the permission of CSA Standards from CSA's C22.1-09 Canadian Electrical Code, Part I (21st Edition), Safety Standard for Electrical Installations which is copyrighted by Canadian Standards Association, 5060 Spectrum Way, Suite 100 Mississauga, ON L4W 5N6. While use of this material has been authorized, CSA shall not be responsible for the manner in which the information is presented, nor for any interpretations thereof. For more information on CSA or to purchase standards, please visit our website at www.shopcsa.ca or call 1-800-463-6727.